

01272.020596



Copie
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
YASUTOMO WATANABE)	: Examiner: Raquel Yvette Gordon
Appln. No.: 10/617,043)	: Group Art Unit: 2853
Filed: July 11, 2003)	: Patent No.: 6,935,726 B2
For: PRINTING HEAD AND INK JET)	: Issued: August 30, 2005
PRINTING APPARATUS WHICH)	
PERFORMS PRINTING WITH THE)	
PRINTING HEAD)	: November 30, 2005

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Certificate
DEC 02 2005
of Correction

Attention: CERTIFICATE OF CORRECTION BRANCH

REQUEST FOR CERTIFICATE OF
CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

12/01/2005 CNGUYEN 00000056 6935726


01 FC:1811

100.00 DP

DEC 5 2005

Patentee's undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,


Attorney for Patentee
Douglas W. Pinsky
Registration No. 46,994

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

DWP/lw

DC_MAIN 221428v1

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,935,726 B2

DATED : August 30, 2005

INVENTOR(S) : YASUTOMO WATANABE

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 19, "ink" should read --ink--.

COLUMN 3

Line 24, "shorten" should read --shortened--.

Line 30, "wiring line" should read --the wiring lines--.

COLUMN 4

Line 15, "part" should read --parts--.

COLUMN 6

Line 28, "most part" should read --most--.

Line 39, "makes" should read -- make--.

COLUMN 7

Line 1, "portion" should read --portions--.

Line 8, "fashion" should read --fashion--.

Staple
Here
Only!

PRINTER'S TRIM LINE

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,935,726 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,935,726 B2

DATED : August 30, 2005

INVENTOR(S) : YASUTOMO WATANABE

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 19, "ink" should read --ink--.

COLUMN 3

Line 24, "shorten" should read --shortened--.

Line 30, "wiring line" should read --the wiring lines--.

COLUMN 4

Line 15, "part" should read --parts--.

COLUMN 6

Line 28, "most part" should read --most--.

Line 39, "makes" should read -- make--.

COLUMN 7

Line 1, "portion" should read --portions--.

Line 8, "fashion" should read --fashion--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,935,726 B2

No. of add'l. copies
@ 30¢ per page

